



# High-Power RMS™ O-ring, Spacer & Insulator Guide


## 29mm High-Power RMS




Aft O-ring  
1" x 1/16"




Forward O-ring  
1" x 3/32"




Delay O-ring  
21mm x 3mm



Forward Seal Disk  
O-ring  
15/16" x 1/16"




Forward & Aft Insulators




Forward Delay  
Spacer


## 38mm High-Power RMS




Aft O-ring  
1-3/8" x 3/16"




Forward O-ring  
1-3/8" x 1/8"




Delay O-ring  
21mm x 3mm



Forward Seal Disk  
O-ring  
1-5/16" x 1/16"




Forward & Aft Insulators




Forward Delay  
Spacer

## 54mm High-Power RMS




Forward & Aft O-rings  
2" x 1/8"




Nozzle O-ring (Small)  
1" x 1/16"

Liner O-ring  
2" x 1/16"




Delay O-ring  
1.17" x .123"



Forward Delay  
Spacer

Forward Seal Disk  
O-ring  
1-7/8" x 1/16"



Forward & Aft Insulators

